

uCANca - Bug #800

Wrong ODS import

05/01/2018 02:37 AM - Txinto Vaz

Status:	New	Start date:	
Priority:	Normal	Due date:	
Assignee:	Txinto Vaz	% Done:	0%
Category:		Estimated time:	0.00 hour
Target version:		Spent time:	0.00 hour
Description			
When importing from ODS, a SCL flow is input and SDA is bidir. The flows are correctly imported, but the subsystem flows in the connector have exchanged their directions.			